




## Long Cable Testing


This article describes how to test very long cables. The standard autotest is supported by the TestPro up to 600m. There is also a special test mode for cables from 500m to 1000m in length. These situations are becoming more common with the growth in Cat 3 IoT and low speed building automation applications.

### 1. Press Settings


From the home screen, press the Project softkey




### 2. Press Certifier/Validator Settings



### 3. Select “Long Cable”




### 4. Press Limit




### 5. Press Enter.

Then press return until you get to the main screen



### 6. Repeat this process for the Remote unit as well

## 7. Press Cable Certification



## 9. Results are displayed



## 8. Press Autotest

